

SECTION VI REACTIVITY DATA			
STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	
INCOMPATIBILITY (Materials to avoid)			
HAZARDOUS DECOMPOSITION PRODUCTS HF Vapors, H ₂ (from contact with metals).			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	
SECTION VII SPILL OR LEAK PROCEDURES			
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Do not breathe vapor, get in eyes, on skin or on clothing. Keep personnel upwind of spill & do not enter area unless equipped with full protective equipment & self-contained breathing apparatus.			
WASTE DISPOSAL METHOD Flush immediately with water, neutralize with lime & flush again with water. Run-off to sewer may create toxic hazard; notify authorities.			
SECTION VIII SPECIAL PROTECTION INFORMATION			
RESPIRATORY PROTECTION (Specific Type) None for normal use. Self-contained breathing apparatus for severe exposure (tank cleaning)			
VENTILATION	LOCAL EXHAUST Maintain adequate ventilation MECHANICAL (General) (Forced draft ventilation. Scrubbers for fume control.)		SPECIAL Exhaust systems should be located adjacent to source of fumes & remotely discharged.
PROTECTIVE GLOVES Rubber or plastic coated gloves covering forearms.			
EYE PROTECTION Chemical safety goggles or face shields.			
OTHER PROTECTIVE EQUIPMENT Hard hat, rubber shoes, rubber apron, long sleeved shirt & trousers of wool or "ORLON". In emergencies or work with considerable exposure, wear full rubber suit with hood.			
SECTION IX SPECIAL PRECAUTIONS			
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store in well ventilated buildings or sheds. Protect against heat & physical damage. Do not get in eyes, on skin, on clothing. Do not breathe vapor. Keep container closed. Wash thoroughly after handling.			
OTHER PRECAUTIONS Before handling, obtain & thoroughly read MCA-SD-25			

E-18963

Date: 11/77

For more information refer to: Du Pont Storage & Handling Bulletin (A-72709)
Manufacturing Chemists Association SD-25

